



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 25, 2011

Reviewed: 

Mine Name: Tejon Quarry #4 (aka Burgundy Pit)	Permit Number: S/027/0117
Operator Name: David Weston, Stone Resources LLC	Inspection Date: May 11, 2011
Inspector(s): Peter Brinton	Time: afternoon
Other Participants: Jerry Mansfield, BLM-Fillmore	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit fee: Current

Bond Renewal Date: 12/15/2015

Bond Amount: \$16,300

Purpose of Inspection: To evaluate site for bond release following Mr. Weston's additional reclamation

Inspection Summary:

Refer to the previous inspection report (March 30, 2011) for background on this site.

Jerry Mansfield and I visited the site to evaluate the most recent reclamation performed by Mr. Weston. Additional work had been done to berm the road in order to discourage direct vehicle access to the pit. Additional earthwork was also done to improve the area above the pit (recontouring some piles and berms), and the area above the pit had been seeded. The quarry area remains open as seen during the previous inspection, and waste rock piles surround the pit as before. Site conditions meet the requirements of the designated post-mining land use at the site, as specified by the BLM.

Conclusions and Recommendations:

The BLM has indicated their acceptance of the reclamation (as it meets their specified post-mining land use), and it is recommended that the Division release the remaining bond.

Inspector's Signature



PNB: pbb

cc: David Weston, Stone Resources LLC

Jerry Mansfield, BLM-Fillmore

O:\M027-Millard\S0270117-Tejon Quarry No4\inspections\INSP-05112011.docx

